



**GEHSR/L** : External machining holders, for Swiss-type automatics



Designation	h	W min	W max	Tmax-r	b	l1	f	A	l2	F1	H2
GEHSL 8-1	8	1.4	1.9	2	8	120	7.1	1	17	7	12
GEHSR 8-1	8	1.4	1.9	2	8	120	7.1	1	17	7	12
GEHSL 8-2	8	2.2	3.2	6.8	8	120	7.1	1.8	17	7	12
GEHSR 8-2	8	2.2	3.2	6.8	8	120	7.1	1.8	17	7	12
GEHSL 10-2	10	2.2	3.2	6.8	10	120	9.1	1.8	17	7	14
GEHSR 10-2	10	2.2	3.2	6.8	10	120	9.1	1.8	17	7	14
GEHSL 12-2	12	2.2	3.2	6.8	12	120	11.1	1.8	17	8	16
GEHSR 12-2	12	2.2	3.2	6.8	12	120	11.1	1.8	17	8	16
GEHSL 16-2	16	2.2	3.2	6.8	16	120	15.1	1.8	20	8	20
GEHSR 16-2	16	2.2	3.2	6.8	16	120	15.1	1.8	20	8	20
GEHSL 20-2	20	2.2	3.2	6.8	20	120	19.1	1.8	20	-	24
GEHSR 20-2	20	2.2	3.2	6.8	20	120	19.1	1.8	20	-	24
GEHSL 25-2	25	2.2	3.2	6.8	25	120	24.1	1.8	20	-	29
GEHSR 25-2	25	2.2	3.2	6.8	25	120	24.1	1.8	20	-	29