




## Complete Machining Solutions







A standard connecting plate that can be assembled easily on most CNC spindle machines with a DIN2079 interface. This connecting plate enables the use of ITSBORE components with MB connection by using any standard adapter with four screws. It is affixed directly on the machine spindle.